

**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	Facility Entrance	NE	Parking and Landscaped Areas of Facility. Note Administration Unit in Background



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



<b>Date</b>	<b>Viewpoint</b>	<b>View Direction</b>	<b>Description</b>
07.08.2003	Parking Lot Southwest of Administration Unit	NE	Administration Unit and Associated Parking Lot



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



<b>Date</b>	<b>Viewpoint</b>	<b>View Direction</b>	<b>Description</b>
07.08.2003	Administration Unit Parking Lot	S	Administration Unit and Associated Parking Lot

**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



**Date**  
07.08.2003

**Viewpoint**  
Lower Parking Lot

**View Direction**  
NW

**Description**  
South Side of Lower Unit and Lower Parking Lot



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	Parking Lot to the West of the Lower Unit	E	Lower Parking and Landscaped Areas South of Lower Unit. Note Shipping Area Doors on West Side of Lower Unit



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	Lower Unit Parking Lot	N	South Side of Lower Unit. Note Protective Barrier Surrounding Well in Center of Photograph



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



**Date**  
07.08.2003

**Viewpoint**  
Lower Unit Parking Lot

**View Direction**  
NE

**Description**  
South Side of Lower Unit



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	Parking Lot to the West of the Lower Unit	N/NE	Paved and Landscaped Areas Surrounding Central and Lower Units. Note Change in Elevation Between Central and Lower Units.



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	Facility Entrance	E	South Side of Central Unit. Baghouse Dust Collectors Located in Red Brick Building (Left-Center of Photograph). Doors to Dock #2 (Rear-Center of Photograph).



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	East of Building 12	S	East Side of Site Property. Note Monitoring Wells in Foreground, and Stacked Wood Pallets in Gravel Area. Also Note Interstate Container Corporation to the South of the Site Property.



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	Assembly and Distribution Center Parking Lot (225 Peach Street, North Pointe Business Center, Ontelaunee Township, Pennsylvania)	-	Assembly and Distribution Center



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



**Date**  
07.08.2003

**Viewpoint**  
Upper Parking Lot

**View Direction**  
SE

**Description**  
Roof of Central Unit



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



Date	Viewpoint	View Direction	Description
07.08.2003	Upper Parking Lot	S	Roof of Central Unit. Note Dust Collection Pipe Placed Along Center of Roof.



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



<b>Date</b>	<b>Viewpoint</b>	<b>View Direction</b>	<b>Description</b>
07.08.2003	Upper Parking Lot	SW	Roof of Central Unit. Note Dust Collection Pipe Placed Along Center of Roof, and 3-Story Red-Brick Office Building.



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



**Date**  
07.08.2003

**Viewpoint**  
North Side of Central Unit

**View Direction**  
E/SE

**Description**  
Dust Collection System Components



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



<b>Date</b>	<b>Viewpoint</b>	<b>View Direction</b>	<b>Description</b>
07.08.2003	North Side of Central Unit	E	Dust Collection System Components. Note Electrical Transformer Area in Foreground



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



**Date**  
07.08.2003

**Viewpoint**  
North Side of Central Unit

**View Direction**  
S

**Description**  
Electrical Transformer Area



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



**Date**  
07.08.2003

**Viewpoint**  
South Side of Lower Unit

**View Direction**  
N

**Description**  
Electrical Transformer Area



**PHOTODOCUMENTATION**  
**Baldwin Hardware Manufacturing Corporation**  
**841 East Wyomissing Boulevard, Reading, Pennsylvania**



<b>Date</b>	<b>Viewpoint</b>	<b>View Direction</b>	<b>Description</b>
07.08.2003	Gravel Area East of Building 12	W	Dust Collection System. Note Dock #5 Area (Doors) in Right-Center of Photograph